

Eversource Tree Removal Control Form

Contract Arborist: **Brande Tarantino** Sheet #: **2**
 Date Planned: **10/21/15** Town: **Bedford** Circuit #: **533-H7**

Pole # -	Address	Perm Type	1.5" - 6"	6" - 12"	12" - 18"	18" - 24"	24" - 30"	30"-36"	36"+	Comments	PUB/ PRIV
25/21A to 22A	Burlington Rd					1 red maple				decay at joint of major leaders, dead stem at base, leans toward wires	Public/ Conservation
25/22A to 23A	Burlington Rd				1 Ailanthus					cavity on backside of central leader	Public/ Conservation
25/23A to 24A	Burlington Rd	no, monitor			1 oak					leans toward wires, growing around metal fence, dead leader	Public/ Conservation
25/ 25A to 26A	1 Earl St on Burlington Rd					1 white pine				extensive decay	Public/ Conservation
25/ 26A to 27A	1 Earl St on Burlington Rd								1 ash	included bark at major joint near base of trunk and leader nearest wires has a cavity (homeowner permission)	Private/ Conservation
25/20 to 21	85 Old Burlington Rd across 85 Old Burlington Rd					1 oak				growing under wires & covered with vines, central leader is very close to wires (homeowner permission)	both ?
25/20	Old Burlington Rd						1 ash			large cavity on backside of trunk, leans toward pole & wires from across road	Conservation
112/ 1 to 2	4 Mill Dam Rd				1 red maple					leans hard on Hendrix cable, wound on trunk (homeowner permission) sewer station	Private/ conservation
Totals			0	0	2	3	1	0	1		

Approval by Tree Warden _____



Date: _____

12/17/15

Eversource Tree Removal Control Form

Contract Arborist:

Brande Tarantino

Street:

Sheet #:

Totals

Date Planned:

10/21/15

Town:

Bedford

Circuit #:

533-H7

Public/ Conservation Totals	1.5" - 6"	6" - 12"	12" - 18"	18" - 24"	24" - 30"	30"-36"	>36"	
	0	1	4	6	4	3	1	
	Grand Total							19

Approval by Tree Warden



Date:

12/17/15

Eversource Tree Removal Control Form

Contract Arborist:

Brande Tarantino

Street:

Sheet #:

2

Date Planned:

10/21/15

Town:


Bedford

Circuit #:

533-H8

Pole # - Pole #	Hse #	Perm Type	1.5" - 6"	6" - 12"	12" - 18"	18" - 24"	24" - 30"	30" - 36"	>36"	Comments	PUB/ PRIV
16/68 to 69	across 230 Hartwell Rd			1 dead spruce						dead	public
16/70	across 230 Hartwell Rd				1 aspen					dead	public
12/9	29 Concord Rd						1 ash			ash with decay at base of trunk, cavity at base of central leader which is within clearance specifications of primary conductors	public
12/24	89 Concord Rd					1 hickory				hard contact to primary conductor (signed permission from abutter)	public
14/43	243 Davis Rd					2 silver maple				1 tree and 1 large leader, one is bent over & within clearance specs, other has cavity in major leader which is hard on primary conductor (signed permission from homeowner)	private?
14/72 to 73	before 391 Davis Rd					1 oak				major leader is hard on primary conductor (burn, sleeve on wire), other major leader is very close (no contact from homeowner)	public?
14/85 to 86	435 Davis Rd				1 locust	2 black locust				dead, dead leaders/poor health, leans toward primary conductors (signed permission from abutter)	public
8/14 to 15	82 Carlisle Rd		0	1	2	1 red maple	1	0	0	cavity/decay in major leader leaning toward primary conductors (landowner permission)	private/conservation

Approval by Tree Warden



Date:

12/12/15

Eversource Tree Removal Control Form

Contract Arborist: Brande Tarantino Street: _____ Sheet #: 3
 Date Planned: 10/21/15 Town: Bedford Circuit #: 533-H8

Pole # - Pole #	Hse #	Perm Type	1.5" - 6"	6" - 12"	12" - 18"	18" - 24"	24" - 30"	30"-36"	>36"	Comments	PUB/ PRIV
8/35 to 36	108-B Carlisle Rd					1 oak				leans hard on primary conductor	public
8/41	201 Carlisle Rd							1 white pine		very close proximity to 2 sets of primary conductors and pole	public
8/43 to 44	211 Carlisle Rd							1 white pine		very close proximity to 2 sets of primary conductors (signed permission from abutter)	public
8/46 to 47	225 Carlisle Rd								1 white pine	hard contact to primary conductors, very close to another (signed permission from abutter)	public
8/53 to 54	237 Carlisle Rd							1 white pine		poor form/3 main leaders, cavity in leader within clearance specifications of primary conductors (signed permission from abutter)	public
8/59 to 60	273 Carlisle Rd						1 oak			declining health, dead leaders & branches (signed permission from abutter)	both?
10/74 to 75	after 339 North Rd					1 hickory				decay/hollow at base of trunk (barbed wire embedded in bark)	public
10/74 to 75	after 339 North Rd		0	0	2 white pine	1 white pine	3	1	3	1 dead; others very close proximity to primary conductors	public

Approval by Tree Warden _____



Date: _____

12/17/15

Eversource Tree Removal Control Form

Contract Arborist: Brande Tarantino Street: _____ Sheet #: 5
 Date Planned: 10/21/15 Town: Bedford Circuit #: 533-H8

Pole # - Pole #	Use #	Perm Type	1.5" - 6"	6" - 12"	12" - 18"	18" - 24"	24" - 30"	30" - 36"	>36"	Comments	PUB/ PRIV
32/105 to 106	b/wm 536 & 538 Springs Rd			1 red maple	1 red maple					6-12" in hard contact to primary conductors, 12-18" in hard contact to secondary wires & wound at base	public
32/106 to 107	b/wm 536 & 548 Springs Rd			1 oak						hard contact to primary conductors	public
32/113 to 114	across 554 Springs Rd					1 white pine				dead	public
32/107 to 108	across 548 Springs Rd						1 oak			long crack on trunk, wound on leader leaning toward conductors	public
32/110 to 111	across 552 Springs Rd			1 oak leader						long leader with dead limb extending over primary conductors	public
32/111 to 112	across 552 Springs Rd	no, monitor				1 oak				hollow trunk, dead central leader. Tree leans toward conductors	public
32/114 to 115	556 Springs Rd				1 white pine					dead, leans toward wires from across street	public
32/116 to 117	558 Springs Rd					1 oak leader				only remove leader in hard contact with primary electrical wires	public
			0	3	2	3	1	0	0		

Approval by Tree Warden _____ Date: 12/17/15

Eversource Tree Removal Control Form

Contract Arborist:

Brande Tarantino

Street:

Sheet #:

Totals

Date Planned:

10/21/15

Town:

Bedford

Circuit #:

533-H8

	1.5" - 6"	6" - 12"	12" - 18"	18" - 24"	24" - 30"	30"-36"	>36"
Public/ Conservation Totals	2	9	18	19	3	3	2

Grand Total 56

Approval by Tree Warden



Date:

12/12/15